









1. ON THE SHORT END OF EACH BUILDING IS AN A/C COMPOUND.
2. EACH A/C COMPOUND HAS A "CHASE" THAT RUNS UP THE BUILDING'S EXTERIOR WHEREIN THERE ARE VARIOUS UTILITY LINES.
3. EACH CHASE HAS A COVER THAT GIVES ACCESS TO THE CHASE.
4. SOME UTILITY CONTRACTORS HAVE BEEN CARELESS IN REMOVING/REPLACING THE COVERS AND HAVE DAMAGED THEM.
5. BELOW WERE ALL OF THE DAMAGED COVERS THAT WERE IDENTIFIED AND REPAIRED.

**DAMAGED CHASE COVERS BY CODE. EXAMPLE. 7E: EAST SIDE OF BUILDING-7.**

1N	7E	7W	9E
			
9W	10W	11S	12E
			
12W	13E		
